

Subcontractor: KODAK			
Table B-1 HARDWARE			
CLIN	Model/ID	Description	IW2 Price
CI1001		CLIN deleted as of 04/02/01	
CI1002	126-8622	Kodak DirectView Computed Radiography System CR 800	\$ 79,800
CI1003	158-7096	Kodak Enhanced Visualization Processing Software (EVP) (CR400)	\$ 10,500
CI1004	893-2782	Kodak Enhanced Visualization Processing Software (EVP) (CR800)	\$ 10,500
CI1005	863-5062	DICOM Storage SSCU Software (CR 800)	\$ 4,200
CI1006	870-2607	DICOM Worklist Management and Worklist Display (CR 800)	\$ 8,400
CI1007	874-8907	Kodak Black Surround Software (CR 800)	\$ 4,116
CI1008		CLIN deleted as of 06/22/01	
CI1009		CLIN deleted as of 06/22/01	
CI1010		CLIN deleted as of 06/22/01	
CI1011	876-3799	Cassette 35 x 43 with General Purpose Screen (CR 400)	\$ 1,508
CI1012		CLIN deleted as of 04/02/01	
CI1013		CLIN deleted as of 04/02/01	
CI1014		CLIN deleted as of 04/02/01	
CI1015		CLIN deleted as of 04/02/01	
CI1016		CLIN deleted as of 04/02/01	
CI1017		CLIN deleted as of 06/22/01	
CI1018		CLIN deleted as of 04/02/01	
CI1019	168-6005	Cassette 35 x 43 with General Purpose Screen (CR 800)	\$ 1,607
CI1020	844-2782	Cassette 35 x 35 with General Purpose Screen (CR 800)	\$ 1,517
CI1021	848-5823	Cassette 24 x 30 with General Purpose Screen (CR 800)	\$ 1,071
CI1022	113-5649	Cassette 18 x 24 with General Purpose Screen (CR 800)	\$ 893
CI1023	887-4372	Cassette 18 x 24 with High Definition Screen (CR 800)	\$ 1,071
CI1024	880-7745	Cassette 24 x 30 with High Definition Screen (CR 800)	\$ 1,250
CI1025		CLIN deleted as of 06/22/01	
CI1026	187-9345	Modem for Service and Support High Speed	\$ 669
CI1027	135-0503	Remote Operations Panel (CR 800)	\$ 6,694
CI1028		CLIN deleted as of 04/02/01	
CI1029		CLIN deleted as of 04/02/01	
CI1030		CLIN deleted as of 04/02/01	
CI1031		CLIN deleted as of 04/02/01	

Subcontractor: KODAK			
Table B-1 HARDWARE			
CLIN	Model/ID	Description	IW2 Price
CI1032		CLIN deleted as of 06/22/01	
CI1033	810-8300	Imaging Network Consulting and Planning	\$ 210
CI1034	134-6477	Imaging Network Assessment Service	\$ 210
CI1035	830-5476	Imaging Network Design Service	\$ 168
CI1036	111-8652	Imaging Network Implementation Service	\$ 168
CI1037	113-4378	KODAK Image Network Tier 1C (Isolated LAN)	\$ 10,500
CI1038	136-0478	KODAK Image Network Tier 2A (Isolated LAN)	\$ 15,330
CI1039	190-2055	KODAK Image Network Tier 2B (Isolated LAN)	\$ 18,186
CI1040	133-7476	KODAK Image Network Tier 3A (100Base TX Enet)	\$ 16,968
CI1041	121-2596	KODAK Image Network Tier 3B (100Base FX Enet)	\$ 18,312
CI1042	140-6149	KODAK Image Network Tier 3C (Gbit Enet)	\$ 18,900
CI1043	117-3905	KODAK Image Network Tier 4A (100Base TX Enet)	\$ 22,008
CI1044	122-3049	KODAK Image Network Tier 4B (100Base FX Enet)	\$ 23,016
CI1045	167-8523	KODAK Image Network Tier 4C (Gbit Enet)	\$ 23,520
CI1046	117-0976	Kodak DirectView Computed Radiography System CR 900	\$ 122,719
CI1047		CLIN deleted as of 06/22/01	
CI1048	103-8801	Kodak DirectView DR 5000 System	\$ 334,688
CI1049	851-9530	Kodak DirectView DR 9000 System	\$ 388,238
CI1050	828-0638	Kodak DirectView Floating Top Table / For DR 9000 System	\$ 37,931
CI1051	124-0514	Kodak Direct View Titl Stretcher / For DR 9000 System	\$ 22,313
CI1052	136-9883	Kodak DirectView Standard Stretcher / For DR 9000 system	\$ 13,388
CI1053	847-5907	Kodak DirectView DICOM Work List Management Software, Version 1.0 for DR 5000/DR 9000 Systems	\$ 8,925
CI1054	887-0859	DICOM Connection Fee	\$ 1,597
CI1055	114-4914	Applications Consulting - Travel Charge	\$ 420
CI1056	132-0720	Applications Consulting - 4 Hour Block	\$ 840
CI1057	174-9662	Applications Consulting - 8 Hour Block	\$ 1,344
CI1058	116-1306	Applications Consulting - 24 Hour Block	\$ 4,032
CI1059	189-4559	Applications Consulting - 40 Hour Block	\$ 6,720
CI1060	156-6736	Applications Consulting - 80 Hour Block	\$ 13,440
CI1061	100-6949	CR Fundamentals - CR101-1 Day	\$ 1,470
CI1062	141-4580	CR with Kodak DirectView CR800 Systems - 2 Days	\$ 2,646
CI1063	129-8900	Digital Imaging Workflow Consultation - 1 Day	\$ 1,890

Subcontractor: KODAK			
Table B-1 HARDWARE			
CLIN	Model/ID	Description	IW2 Price
CI1064	112-3967	CR and DR Image Quality Optimization - 1 Day	\$ 1,890
CI1065	114-1852	Advanced Image Processing with CR800 - 3 Days	\$ 3,780
CI1066	829-7624	KODAK Image Network Tier 1A(Isolated LAN)	\$ 1,848
CI1067	115-4236	KODAK Image Network Tier 1B(Isolated LAN)	\$ 6,342
CI1068	885-8383	Tier 1 / Tier 2 solutions (w/o Uplink) (Not available for Tier 1a)	\$ 3,213
CI1069	825-3114	Tier 3 / Tier 4 solutions (with Uplink)	\$ 6,489
CI1070	168-2681	Kodak Image Network Support (Non-contract support)	\$ 210
CI1071	152-5153	Kodak Image Network Support Plus (contract support)	\$ 168
CI1072	803-1783	Kodak Image Network Mangement	\$ 168
CI1073	120-3561	Kodak Medical Imaging Program Mgt Services/On Site	\$ 231
CI1074	182-6254	Kodak Medical Imaging Program Mgt Services/Off Site	\$ 210
CI1075	162-8742	DryView 8100 Laser Imager - PACS Link	\$ 43,366
CI1076	819-1181	DryView 8200 Laser Imager - PACS Link	\$ 49,099
CI1077	132-7204	DryView 8300 Laser Imager - PACS Link	\$ 23,160
CI1078	811-6949	DryView 8500 Laser Imager - PACS Link	\$ 63,022
CI1079	113-4295	DryView 8610 Laser Imager - PACS Link	\$ 57,289
CI1080	860-5909	DryView 8700 Laser Imager - PACS Link	\$ 63,022
CI1081	838-1543	PACS Link System - Print connection for DryView 8300 Laser Imager	\$ 5,733
CI1082	801-0068	PACS Link System - Print connection for DryView Large format and DryView 8610 Laser Imagers	\$ 9,009
CI1083	806-0592	PACS Link System - Print connection for Third-party DICOM 3.0 equipment	\$ 1,597
CI1084	887-8472	DICOM Store Output Software	\$ 4,095
CI1085	897-9841	Software for HIS/RIS Connection	\$ 4,095
CI1086	849-0096	DICOM Store Output Software	\$ 5,733
CI1087	835-9135	Software for HIS/RIS Connection Upgrade	\$ 5,733
CI1088	862-4272	PACS Link Laser Imager Upgrade Package	\$ 11,876
CI1089	868-3260	DryView 8300 PACS Link Lser Imager Upgrade Pkg	\$ 5,733
CI1090	150-9991	PACS Link 9415 Interface for Fuji Computed Radiography (CR)	\$ 24,529

Subcontractor: KODAK			
Table B-1 HARDWARE			
CLIN	Model/ID	Description	IW2 Price
CI1091	830-2648	PACS Link Fuji Computed Radiography (CR) Store/View Connection	\$ 9,009
CI1092	815-3645	DryView 7000 Film Duplicating System	\$ 24,529
CI1093	888-3894	DryView 8500 Laser Imager Dual Printer Package	\$ 39,271
CI1094	113-2497	DryView 8700 Laser Imager Dual Printer Package	\$ 39,271
CI1095	894-0041	3M Fiber Optic Cable	\$ 123
CI1096	118-7996	10M Fiber Optic Cable	\$ 287
CI1097	865-8247	30M Fiber Optic Cable	\$ 410
CI1098	143-5973	60M Fiber Optic Cable	\$ 573
CI1099	878-2450	100M Fiber Optic Cable	\$ 778
CI1100	874-7255	150M Fiber Optic Cable	\$ 1,106
CI1101	134-6923	200M Fiber Optic Cable	\$ 1,290
CI1102	160-6946	250M Fiber Optic Cable	\$ 1,392
CI1103	874-8527	300M Fiber Optic Cable	\$ 1,474
CI1104	894-4522	500M Fiber Optic Cable	\$ 2,293
CI1105	162-5425	Kodak 1200 Desktop Medical Imager	\$ 402
CI1106	122-1928	Kodak 3600 Desktop Medical Imager	\$ 3,566
CI1107	196-7009	Kodak 3600 Desktop Medical Imager / DICOM Package	\$ 10,264
CI1108	114-7370	Kodak 3600 Desktop Medical Imager / Color Video Package	\$ 10,264
CI1109	148-9483	Kodak 3600 Desktop Medical Imager / Digital Package	\$ 10,264
CI1110	100-5842	Kodak 3600 Desktop Medical Imager / Grayscale Video Package	\$ 10,264
CI1111	883-2669	DMI Medical Imager Second Connection Fee	\$ 6,248
CI1112	108-4391	Remote Patient Data Entry Software	\$ 1,160
CI1113	832-4105	DryView 8100 Laser Imager	\$ 40,909
CI1114	138-8164	DryView 8300 Laser Imager	\$ 20,483
CI1115	859-8468	DryView 8700 Laser Imager	\$ 56,470
CI1116	817-0953	DryView 8300 Direct Print Connectoins	\$ 5,733
CI1117	197-7032	Direct Print Connection	\$ 9,009
CI1118	836-2238	Kodak DirectView Total Quality Tool / Starter Kit	\$ 5,880